

<b>Release Date</b>	<b>Version History</b>	<b>Software Update Tools</b>
9-Oct-17	<p>MCU v2.3.0</p> <ul style="list-style-type: none"> <li>• Add support to swap between Left and Right speakers</li> </ul> <p>Wi-Fi v1.1.4</p> <ul style="list-style-type: none"> <li>• Add “Spotify Connect” support (compatibility varies by country)</li> </ul> <p>DSP v0.54</p> <ul style="list-style-type: none"> <li>• No update</li> </ul>	<p>Mac OS X</p> <ul style="list-style-type: none"> <li>• LS50_Wireless_Firmware_Update_Tool_V1.3</li> </ul> <p>Windows</p> <ul style="list-style-type: none"> <li>• LS50W_FW_Upgrade_Tool_V1.1.0.0</li> </ul>
22-May-17	<p>MCU v2.2.1</p> <ul style="list-style-type: none"> <li>• Fixed Wi-Fi network memory occasionally lost after system restarting</li> <li>• Fixed potential left speaker no output issue</li> <li>• Each source has now individual volume memory</li> <li>• Add the ability to disable Auto-Standby time</li> <li>• Other bug fixes and improvements</li> </ul> <p>Wi-Fi v1.1.3</p> <ul style="list-style-type: none"> <li>• Add ALAC format support</li> <li>• Fixed volume control over App issue</li> <li>• Other bug fixes and improvements</li> </ul> <p>DSP v0.54</p> <ul style="list-style-type: none"> <li>• No update</li> </ul>	<p>Mac OS X</p> <ul style="list-style-type: none"> <li>• LS50_Wireless_Firmware_Update_Tool_V1.0</li> </ul> <p>Windows</p> <ul style="list-style-type: none"> <li>• LS50W_FW_Upgrade_Tool_V1.1.0.0</li> </ul>