

Release Date	Version History	Software Update Tools
15-Nov-17	<p>MCU v2.4.0</p> <ul style="list-style-type: none"> Fixed low voltage protection issue causing system or slave error <p>Wi-Fi v1.1.6</p> <ul style="list-style-type: none"> Improved Roon support Various bug fixes that improve app stability Bug fixes to improve firmware upgrade stability <p>DSP v0.54</p> <ul style="list-style-type: none"> No update 	<p>Mac OS X</p> <ul style="list-style-type: none"> LS50_Wireless_Firmware_Update_Tool_V2.0 <p>Windows</p> <ul style="list-style-type: none"> LS50W_FW_Upgrade_Tool_V2.0
9-Oct-17	<p>MCU v2.3.0</p> <ul style="list-style-type: none"> Add support to swap between Left and Right speakers <p>Wi-Fi v1.1.4</p> <ul style="list-style-type: none"> Add "Spotify Connect" support (compatibility varies by country) <p>DSP v0.54</p> <ul style="list-style-type: none"> No update 	<p>Mac OS X</p> <ul style="list-style-type: none"> LS50_Wireless_Firmware_Update_Tool_V1.3 <p>Windows</p> <ul style="list-style-type: none"> LS50W_FW_Upgrade_Tool_V1.1.0.0
22-May-17	<p>MCU v2.2.1</p> <ul style="list-style-type: none"> Fixed Wi-Fi network memory occasionally lost after system restarting Fixed potential left speaker no output issue Each source has now individual volume memory Add the ability to disable Auto-Standby time Other bug fixes and improvements <p>Wi-Fi v1.1.3</p> <ul style="list-style-type: none"> Add ALAC format support Fixed volume control over App issue Other bug fixes and improvements <p>DSP v0.54</p> <ul style="list-style-type: none"> No update 	<p>Mac OS X</p> <ul style="list-style-type: none"> LS50_Wireless_Firmware_Update_Tool_V1.0 <p>Windows</p> <ul style="list-style-type: none"> LS50W_FW_Upgrade_Tool_V1.1.0.0